



HEBER LTD.

Belvedere Mill
 Chalford
 Stroud
 Glos, GL6 8NT, UK
 Tel: +44 (0) 1453 886000
 Fax: +44 (0) 1453 885013
 Email: support@heber.co.uk
 Web: http://www.heber.co.uk

Technical Bulletin


Silk Screen Erratum on Firefly X10 Evaluation Boards

Firefly X10 Evaluation boards with the Heber part number, **01-16528, Issue 4**, have an incorrectly printed silk screen label on the SEC Meter connector.

The incorrect label on the Firefly X10 Evaluation Board is as follows:

SEC METER	PIN
OP0 (CLOCK)	1
OP1 (DATA TO METER)	2
IP18 (DATA FROM METER)	3
OP3 (RESET)	4
+12V	5
GND	6

The correct pinouts for the SEC Meter connector are as follows:



Further Information

If you require any further information please contact: support@heber.co.uk